



CHEM-SECURITY SYSTEMS, INC.

10602 NE 38th Place • Kirkland, Washington 98033 • (206) 827-0711

8/12/1986

WA 2917

August 12, 1986

AUG 13 1986

FILE COPY

Mr. Rick Morton
Chemical Processors, Inc.
5501 Airport Way South
Seattle, WA 98108

Re: Waste Profile Sheet: E41865 - Expires October 1, 1986

Dear Rick:

As part of our periodic re-examination of wastes received at the Arlington facility, we need your help to recertify the waste profile sheet(s) listed above. If your company will continue generating the referenced waste stream(s) for disposal, please complete the steps below as soon as possible.

1. Redo the Profile

Enclosed is a copy of your original waste profile sheet and a blank profile, having the same profile number as the original, for your use in recertifying the waste. Please look over the old copy, make any necessary changes, and fill out the new form for the waste as it currently exists. Make sure the profile is completely filled out and note the following:

- a. Section C - Please make sure you characterize 100 percent of the waste.
- b. Sections D and E - Use "0" if there is no value. If there is a value, please put it in. "N/A" is not an acceptable response, nor are blanks acceptable.
- c. Please check a category in Section G under "Other Hazardous Characteristics".
- d. Make sure that the proper DOT shipping name is used for any state or federally regulated waste. The name must be taken from 49 CFR 172.101. If you are unsure, discuss it with your Sales Representative.

USEPA RCRA



3012715

Mr. Rick Morton
August 12, 1986
Page 2

2. Obtain Sample and Send Sample and Profile to CSSI

Obtain a one-quart sample. Properly package it (usually in an inner screw-top polyethylene plastic coated glass container, packed in a secure outer container or box with absorbant), and label the package as shown on the Certification of Representative Sample (CRS).


Fully complete the Certification of Representative Sample, including the sample label. This label and the label on the sample itself must be identical. Also, the sample must be taken by an EPA approved method.

Send the certification and the front three profile sheets to the Arlington facility. Their address is on the back of the profile sheet. The fourth copy should be sent to this office and the fifth should be kept for your records.

Please call me if you have any questions. We appreciate your help and cooperation in this matter.

Sincerely,

CHEM-SECURITY SYSTEMS, INC.



Marcia Charlton
Customer Service Representative

MC:mb

Enclosures